

(4) Empty the barrel, then rinse with clean water. Drip dry and use.

UTILIZATION AFTER STORAGE OF MORE THAN ONE MONTH

STING BARRELS INTO SPEC

Keep the barrel wrapped in plastic film. Store in a draft free location with humidity greater than 75%.



COLD WATER 48H

- Fill the barrel entirely with cold water.
- 2 Let the barrel rest for 48 hours.
- 3 Empty the barrel.
- ④ Rinse the barrel with clean water. Drip dry and use.

Made in France using renewable energy.



This barrel will result in one oak being planted in a French forest.



20, RUE DES GILLARDEAUX - 17100 LES GONDS - FRANCE www.tonnelleriebaron.com